

Job Hazard Analysis			JHA # 32	
Job/Task Title: Stilt Use				
Safe Job Procedure:			Revised 1/2024	
This JHA is for the safe and successful use of Stilts to access work area. Special emphasis is placed on housekeeping and being aware of your work area.				
Required PPE: Hard Hat, Safety Glasses, Hi-Vis, Gloves and Work Boots				
Review JHA's 30,31: Covering/ Cleanup, Lock Out-Tag Out (LOTO)				
Step #1 Work Area Inspection				
Steps to Complete Job	Hazards		entive Measures	
Survey and set up the work area.	Workers can be cut on sharp materials, sharp edges, or equipment. Possible trips, falls, and being struck by loose debris or unsecure materials.	1) Hard Hat, Safety Glasses, Hi-Vis, Gloves, and Work Boots.		
		2) Identify, eliminate, or mark all trip hazards such as, open holes, slippery conditions, rolling stock, or changes in elevations.		
		3) Correct or note any changes in work area since last leaving it.		
		4) Pickup loose mat from work area.	erials and remove debris	
Identify any stored energies in the work	Workers could release unknown or unsuspected	1) Relocate stored of from work area.	energy components or system	
area that could be released due to the work being performed, or by being damaged.	energy due to damage, removal of system components, or exposure of system components.	2) Deenergize and install LOTO procedures to stored energy source.		
		Install bulletproofing or mitigation to protect stored energy source.		
		4) Barricade and tag area around stored energy source.		
Walk area to ensure that there is adequate lighting and electrical power supply.	Lack of lighting can impair the ability to see, causing trips, falls, cuts, etc. Lack of sufficient electrical power can cause circuit overloads and excessive number of electrical cords in the area.	1) Have temporary work begins.	task lighting provided before	
		2) Have temporary power provided before work begins.		
		3) Minimize electrical cords in area. Verify the cords in use are rated for their intended use.		
		4) All cords and lighting to be GFCI protected.		



FRED SHEARER & SONS, INC. ESTABLISHED 1916

Coordinate work in the	Possible confusion and	1) Communicate with other trades to avoid	
area with other trades.	conflict due to multiple	creating a hazardous situation by trade stacking.	
	trades working in a limited	Coordination.	
	area.		
Step #2 Use of Stilts			
Steps to Complete Job	Hazards	Preventive Measures	
Inspect stilts before use	Worker has the potential	1) Stretch and flex before beginning of the shift	
and set up work area for	to be exposed to cuts,	and after lunch. Stretch throughout the shift	
safe operation.	slips, trips, and falls.	when needed to reduce or eliminate muscle	
		strains.	
		2) Thoroughly inspect stilts for any defects and	
		fill out a daily stilt inspection form before use.	
		3) Excellent housekeeping is a must. Remove all obstacles and trip hazards from working areas	
		prior to mounting stilts. Depending on the job,	
		this may need to be done each time you put stilts	
		on. In high traffic areas, consider controlling task	
		areas with caution tape to keep stilt users safe.	
		4) Never use stilts when working within 10 feet	
		of a leading edge.	
		5) Stilts that have been altered in any way must	
		be red tagged and taken out of service.	
Mounting Stilts.	Worker will be exposed to	1) To put stilts on, use a baker or roll and fold	
	trip and fall hazards.	scaffold against a wall with all four wheels	
		locked.	
		2) Ensure area in front of platform is clear of any	
		trip hazards.	
tt i Gilli i)	3) Stand up on stilts and tighten straps again.	
Using Stilts to access	Worker will be exposed to	1) Constantly be aware of changes to your work	
work.	slip, trip, and fall hazards.	2) Continually watch where you are stepping.	
		Running or horseplay is never allowed.	
		4) Clean up mud spills quickly to avoid slippery	
		conditions.	
Dismounting Stilts.	Worker will be exposed to	1) Use a baker or roll and fold scaffold against a	
	slip, trip, and fall hazards.	wall with all four wheels locked when removing stilts.	
		2) Ensure area in front of platform is clear of any	
		trip hazards.	
		3) Strap both stilts together and close calf straps.	
		Store in a designated secure location at the end	
		of the shift.	